




B-B
INPUT SIDE VIEW



Note:
- MAIN RING MUST BE FIXED IN OPERATION WITH
18pcs SCREW M3 St 12.9, TIGHTENING TORQUE 2.2Nm